



PARTS MANUAL

**5445H COM3 TIER 3
COMBINE**


PRINTED BY :
heavy-equipmentmanual.com

5445H COM3

Cutting table trailer

GENERAL

TRAILER BAR 2003.....	5F.00.0
TRAILER 2003.....	5F.00.1
TRAILER LIGHT ARM.....	5F.00.2
TRAILER LIGHT ARM GERMANY ONLY	5F.00.3




5445H COM3

Section: Cutting table trailer
TRAILER BAR 2003

Ref: 5F.00.0

Fig.	P/n	QTY	Name
Notes:			
[5445H]			
1	0424422	1	crank
2	0633637	1	shock absorber
3	7400032	4	washer
4	7412469	4	washer
5	6220867	4	screw
6	6593438	2	nut
7	0493699	1	arm
8	R701116	1	arm
9	6252787	2	screw
10	6234397	4	screw
11	7400034	8	washer
12	R701114	1	plate
13	6594238	4	nut
14	8033689	2	spacer PG11
15	R701113	1	square pulley
16	R699534	1	plate




5445H COM3

Section: Cutting table trailer

Ref: 5F.00.1

TRAILER 2003

Fig.	P/n	QTY	Name
Notes:			
[5445H]			
1	R698921	2	arm
2	R698920	2	stopper
3	7400032	16	washer
4	6594038	8	nut
5	6221467	8	screw
6	6594048	4	nut
7	R701111	2	pin
8	6226167	4	screw
9	R698945	2	support
10	R701137	2	pin
11	7414473	1	washer
12	6506631	1	nut
13	R701110	1	pin
14	6231567	6	screw
15	7400034	4	washer
16	R698943	2	plate
17	6594238	14	nut
18	6231977	2	screw
19	R659414	2	special bushing
20	7812410	2	pin
21	8020230	12	reflector
22	R601344	2	pin
23	0633897	2	rubber
24	R701149	1	support sx/lh/li
25	R701345	1	latch dx/rh/re
26	8020231	2	reflector
27	8020232	2	reflector
28	R701150	1	support sx/lh/li
29	R701344	1	latch dx/rh/re
30	R701133	1	pin
31	7814285	4	pin
32	6231767	4	screw
33	6221260	4	screw
34	0480571		tube
			-> (...)
36	6593438	1	nut
37	7400040	1	spring washer
38	0480581		tyre
			-> (...)
38	0492963		ring
			(...) <-



5445H COM3

Section: Cutting table trailer

Ref: 5F.00.1

TRAILER 2003


Fig.	P/n	QTY	Name
39	0480570		rim
			-> (...)
39	0498951		rim
			(...) <-
40	6594438	10	nut
41	7400036	10	washer
42	R638582	2	cover
43	0562006	2	lock-nut
44	0563006	2	nut
45	0562027	2	spring washer
46	0252420	2	grease gun
47	0480566	2	bearing
48	R695038	2	hub
49	0480567	2	bearing
50	R695040	2	guard

TRAILER LIGHT ARM

Fig.	P/n	QTY	Name
------	-----	-----	------

Notes:
[5445H]

1	8070022	2	side lamp
2	8020240	2	reflector
3	R701127	1	arm
4	0415225	1	spring
5	7414059	1	washer
6	6229867	1	screw
7	8020260	1	triangle
8	7400030	8	washer
9	6210667	8	screw
10	8020230	2	reflector
11	R701125	1	arm
12	8041630	1	cable
13	8055562	2	pipe fitting
14	8035095	2	headlight
15	8035093	2	headlight
16	6594238	1	nut
17	7400034	2	washer
18	6232973	1	screw



5445H COM3

Section: Cutting table trailer


Ref: 5F.00.3

TRAILER LIGHT ARM GERMANY ONLY

Fig.	P/n	QTY	Name
------	-----	-----	------

Notes:
[5445H]

1	8070021	2	side lamp
2	8020240	2	reflector
3	R701127	1	arm
4	0415225	1	spring
5	7414059	1	washer
6	6229867	1	screw
7	0813693	1	plate
8	7400030	8	washer
9	6210667	8	screw
10	8020230	2	reflector
11	R701125	1	arm
12	8014630	1	cable
13	8055562	2	pipe fitting
14	8035095	2	headlight
15	8035093	2	headlight
16	6594238	1	nut
17	7400034	2	washer
18	6232973	1	screw



5445H COM3

Loss monitor

GENERAL

GRAIN LOSS CONTROL SYSTEM.....	5E.00.0
GRAIN LOSS CONTROL SYSTEM.....	5E.00.1
GRAIN LOSS CONTROL SYSTEM.....	5E.00.2
GRAIN LOSS CONTROL SYSTEM.....	5E.00.3
GRAIN LOSS CONTROL SYSTEM.....	5E.00.4
CONTROLS.....	5E.00.5
SWITCH.....	5E.00.6
ELECTRICAL SYSTEM.....	5E.00.7
ELECTRICAL SYSTEM.....	5E.00.8

5445H COM3

Section: Loss monitor

Ref: 5E.00.0

GRAIN LOSS CONTROL SYSTEM

Fig.	P/n	QTY	Name
------	-----	-----	------

Notes:
[5445H]

1	8033681	1	index
2	8033682	1	cable
3	8033683	1	level indicator
4	8033684	1	printed circuit
5	8033717	1	cable
7	8040001	1	pipe fitting
8	8040000	1	pipe fitting
9	8033685	1	cable
10	6593838	22	nut
11	7400030	22	washer
12	R694242	1	support
13	6211467	6	screw
14	8033726	2	spool valve
15	8033686	1	printed circuit
16	8033718	1	level indicator
17	8033723	1	screw
18	8033722	1	magnet
19	8033721	1	spring washer
20	8033729	2	level indicator
21	8033728	1	level indicator
22	6594048	1	nut
25	R687080	1	screw
26	7400032	1	washer
27	6220486	1	screw
29	6211877	4	screw
30	7266308	4	block
31	6210667	12	screw
32	R693643	2	pipe fitting
33	R692442	2	plate
FOR 5 STRAW WALKERS			
34	R695723	1	support
35	R694661	1	support
35	R696258	1	support
36	0633567	2	insulator
37	R694545	1	support
38	6062814	2	block
39	0629093	1	support
40	8030080	1	cable
41	R694243	1	support
42	R694096	1	cable

GRAIN LOSS CONTROL SYSTEM

Fig.	P/n	QTY	Name
------	-----	-----	------

Notes:
[5445H]

1	8033700	1	index
2	8033701	2	nut
3	8033702	1	support
4	8033703	1	guard
5	8033704	1	screw
6	7400032	3	washer
7	8033706	1	pieces
8	7400029	2	washer
9	8033708	2	screw
10	8033709	2	guard
11	8033710	2	screw
12	8033711	1	support
13	6506234	2	nut
14	8033713	1	cable
15	8033714	2	spool valve
16	8033715	2	fuse
17	8033716	1	printed circuit
18	8033717	1	cable
19	8033718	2	level indicator
20	8033719	1	cable
21	8033720	1	level indicator
22	8033721	8	spring washer
23	8033722	8	magnet
24	8033723	8	screw
25	8033724	6	level indicator
26	6506034	10	nut
27	7414465	11	washer
28	9693802	1	cable
29	6210667	7	screw
30	8033705	1	printed circuit
38	R693269	1	support
39	R693272	1	support
40	R693267	1	support
41	R693265	1	support
42	R693266	1	support
43	R693264	1	support
48	R693274	2	ring
49	R693275	2	ring
51	R693276	1	ring
52	R693277	1	ring
54	R693273	1	plate